

## VT6120/VT6122 Software Package (VNT version): 2.6

### 1. Major changes in this software packages

1.1. Add WinCE 4.2 MSI install.

### 2. Notice

2.1. All the drivers included in this software package are free for the vulnerability of Ethernet frame padding information leakage issue reported by @stake Inc. in Jan 2003.

2.2. WHQL submission number of the Windows NDISM driver (v1.51) for x86/x64 in this software package is 1102158.

### 3. Detailed change note list

#### 3.1. Drivers

Name	Ver.	Support OS	Location	Note
NDIS3/4/5 for X86	1.51	Win95, Win95OSR2, Win98, Win98SE, NT3.51, NT4.0, Windows ME, Windows 2000; Windows XP, Windows Server 2003	Root directory	<ol style="list-style-type: none"> <li>Fix EEPROM embedded/directed write bug for GigaCheck.</li> <li>Add 1 SSID/SVID.</li> <li>Add MSI install for WinCE 4.2.</li> </ol>
NDIS5 for X64		Windows XP, Windows Server 2003 X64 Edition		
NDIS5 for Embedded		Windows XP Embedded SP1	\XPe\	
		Windows CE 4.0/4.2 Windows CE 5.0	\CE4\ \CE5\	
NDIS3F	1.34	Windows For Workgroup 3.11	\WFW311\	<ol style="list-style-type: none"> <li>No version change in this software package.</li> </ol>
NDIS2	1.07	LAN Server DOS Workstations, LANTASTIC, PCNFS, DOS (MS client 3.0)	\LANSVR40.D OS\ \LANTASTI\ \MSLANMAN. DOS\ \PCNFS\	<ol style="list-style-type: none"> <li>No version change in this software package.</li> </ol>
Packet	1.10	DOS (NCSA Telnet client, PCTCP)	\PKTDRVR\	<ol style="list-style-type: none"> <li>No version change in this software package.</li> </ol>

Server ODI (ASM version)	2.01	Netware Server 3.11, 3.12, 4.11, 4.12	\\NETWARE\\SR VRODI.311\\, \\NETWARE\\SR VRODI.312\\, \\NETWARE\\SR VRODI.4\\	1. No version change in this software package.
Server ODI (C version)	2.05	Client 32 for DOS, Netware Server 5.0, 5.1, 6.0, 6.5	\\NETWARE\\C LIENT32\\, \\NETWARE\\SR VRODI.56\\	1. No version change in this software package.
DOS ODI	1.10	DOS (Netware client for DOS)	\\NETWARE\\D OSODI\\	1. No version change in this software package.
MAC OS	1.04	MAC OS X 10.1.x ~ 10.2.x	\\MACOSX\\	1. Modify procedure for servicing interrupt events.
Linux	1.24	Linux x86 Kernel 2.2.x ~ 2.6.12 Linux AMD64 Kernel 2.4.x ~ 2.6.12	\\LINUX\\	1. Code sync with FreeBSD driver. 2. Fixed bug of function "velocity_receive_frame".
FreeBSD	1.20	FreeBSD 3.2, 4.0, 4.11, 4.2, 4.5~4.7, 5.0~5.3, 5.2~5.3 AMD64	\\FREEBSD\\	1. No version change in this software package.
Unixware	1.12	SCO Unixware 7.1, OpenUnix 8	\\UNIXWARE\\	1. No version change in this software package.
SCO5	1.11	SCO Open Server 5.0.4, 5.0.6	\\SCO5\\	1. No version change in this software package.
Solaris	1.10	Solaris 8, 9	\\SOLARIS\\	1. No version change in this software package.
DIAG	1.33	DOS	Root directory	1. No version change in this software package.
Winsetup	3.18	Win95, Win95OSR2, Win98, Win98SE, NT3.51, NT4.0, Windows ME, Windows 2000, Windows XP, Windows Server 2003, Windows XP X64 Edition, Windows Server 2003 X64 Edition	Root Directory, \\WINSETUP\\	1. No version change in this software package.

### 3.2. Application utilities

Name	Ver.	Support OS	Location	Note
GigaCheck	2.21	Win95, Win95OSR2, Win98, Win98SE,	\\GigaCheck\\	1. Miniport driver (1.51). 2. Winsetup (3.18).

		NT4.0, Windows ME, Windows 2000, Windows XP, Windows Server 2003		
DMI-GE	1.22	Win95, Win95OSR2, Win98, Win98SE, NT4.0, Windows ME, Windows 2000, Windows XP, Windows Server 2003	\\DMI-GE\	1. miniport driver (1.51). 2. winsetup (3.18).
VSNMP-GE	1.23	Win98, Win98SE, NT4.0, Windows ME, Windows 2000, Windows XP, Windows Server 2003	\\VSNMP-GE\	1. miniport driver (1.51). 2. winsetup (3.18).

### 3.3. Drivers/Utilities for Boot ROM users

Name	Ver.	Support OS	Location	Note
Flash	1.08	DOS	\\FLASH\	1. No version change in this software package.
RPL-DOS	1.17		\\RPL\	1. No version change in this software package.
PXE	1.18		\\PXE\	1. No version change in this software package.
PXERPL	1.16		\\PXERPL\	1. No version change in this software package.

### 3.4. Drivers/Utilities for manufacturer, not to release to users

Name	Ver.	Support OS	Location	Note
Ether-debug tool for Windows CE	1.01	Microsoft Windows CE 4.2 & 5.0	\\ETHERTOOL\	1. No version change in this software package.
EEPROM	1.13	DOS	\\EEPROM\	1. Add sub-parameter '-al' which cooperates with command line option '-p' to set the limit of programmed MAC address.

### 3.5. MISC

Name	Ver.	Support OS	Location	Note
UNATTEND	1.02	Windows 9x, NT 4.0, 2000, XP	\\UNATTEND\	1. No version change in this software package.

### 3.6. Application documents

Document	Ver.	Location	Note
GigaCheck User Guide	1.60	\\GigaCheck\	1. No version change in this software package.

DMI-GE User Guide	1.40	\\DMI-GE\	1. No version change in this software package.
VSNMP-GE User Guide	1.50	\\VSNMP-GE\	1. No version change in this software package